

Zechlaser Austria

SLOW FLOW CO² LASER – Made in Austria

ZL200

ZL400

Technical Features

Output wavelength 10.59 microns
Output power 200 watt, 400 watt
Electrical power input 380-400 VAC, 50 Hz
PC controlled CO² Laser floating resonator

Low service and spare parts costs
Minimal electrical power consumption
Minimum gas consumption 10 l/h



Resonator



Electric-Case



ZL400

Automatic start-up
Continuous power variation
Output power control
Gas, temperature and interlock alarms
Microprocessor controlling/LCD display
extern PC controlled (Windows2000)



Microprocessor

| ZECHLASER CO² Laser - specifications | | SLOW FLOW LASER | |
|---|--|----------------------------|-----------------------------|
| Model | | ZL-200 | ZL-400 |
| Output range [W] | | 50 - 200 | 50 - 400 |
| Rated power [W] | | 200 | 400 |
| Output power stability [%] | | +/-2 | +/-2 |
| Output wavelength [n m] | | 10.6 | 10.6 |
| Beam diameter (1/e²)[mm] | | 14 | 15 |
| Beam divergence [mrad] | | <1.5 | <1.5 |
| M² factor at rated power (Mode Master) | | <1.4 | <1.4 |
| Polarization | | linear | linear |
| Beam pointing stability [mrad] | | ≤ 0,2 | ≤ 0,2 |
| Operation | | cw | cw |
| Pulse repetition (Hz) | | 10 - 1000 | 10 - 1000 |
| Minimum pulse duration [m s] | | 150 | 150 |
| Gas composition [He/N₂/CO₂] | | 82/13,5/4,5 | 82/13,5/4,5 |
| Gasconsumption l/hour | | 10 | 15 |
| Dimensions [mm] | | 2750x400x600 | 2750x600x800 |
| Weight (kg) | | 280 | 470 |
| Water - Cooling 2 Bar | | 2kW - 8l/min 18° +/- 1° | 4kW - 12l/min 18° +/- 1° |
| Electrical power | | 3x400V/3kW | 3x400V/5kW |
| Microprocessor controlling extern PC controlled (Windows 2000) | | | |

HIGH POWER AXIAL FLOW CO² LASERS 600 – 3000 WATT



**ZLX6
ZLX10
ZLX20
ZLX30**

Technical Features



Laser Power ON

New Resonator design
Output wavelength 10.59 microns
Output power 700 watt up to 3000 watt
Electrical power input 380-400 VAC, 50 Hz

Low service and spare parts costs
Minimal electrical power consumption
Minimum gas consumption 30 l/h

Automatic start-up
Continuous power variation
Output power control
Gas, temperature and interlock alarms
Microprocessor controlling/LCD display –
extern PC controlled (Windows2000)



High Power Laser





High precision part

High tech components for a long
Life time. We have specialised in
providing for your solutions.
Our equipment reduces your costs and
ensures the perfection of your
products.

| CO₂ INDUSTRIAL FAST FLOW LASER CHARACTERISTICS | | ZECHLASER | |
|---|------------------------|------------------------|--|
| Model | ZLX6 | ZLX10 | |
| Rated output power [W] cw range max. | 600 | 1000 | |
| Wavelength nm | 10600 | 10600 | |
| Beam diameter (1/e²)[mm] | 14 | 16 | |
| Beam divergence [mrad] | 2 | 2 | |
| Mode structure | TEM 01 | TEM01 | |
| Operation | cw | cw | |
| Pulse mode | 10 Hz - 2000 Hz | 10 Hz - 2000 Hz | |
| Minimum pulse duration | 100 | 100 | |
| Beam pointing stability [mrad] | 0,2 | 0,2 | |
| Gas mixture CO₂ - N₂ - He | 6-20-74 | 6-20-74 | |
| Gas mixture consumption | 30 l/h | 35 l/h | |
| Electrical power | 400V 50 Hz 16A | 400V 50 Hz 16A | |
| Water cooling | 16-18°C, 12 liters/min | 16-18°C, 15 liters/min | |
| Cooling power required [kW] | 6 | 10 | |
| Weight [Kg] | 630 | 720 | |
| Dimension [mm] | 2380x750x1100 | 2380x750x1100 | |
| <p>Automatic start-up Continous power variation Output power control Gas, temperature and interlock alarms</p> | | | |
| <p>Microprocessor controlling/LCD display - extern PC controlled (Windows2000)</p> | | | |

Energy supply equipment for ZL6X



| | |
|--------------------|-----------------|
| Type ZL6X | |
| Zech Laser Austria | Name: stromZL6X |

SERVICING AND SAFETY INSTRUCTIONS

Cooling unit

Make sure that the water reservoir is always filled sufficiently and that the water pressure is kept constant during operation. The water pressure should be 2 bar and the temperature should be $18^{\circ} \pm 1^{\circ} \text{C}$.

Laser

The laser itself does not need maintenance. For trouble-free functioning, it is sufficient to ensure that the water pressure is as required (2 bar) and that all connections are fastened properly.

If you notice that there is water of condensation in the laser, because a high humidity of air you must prepare a correspond air conditioning.

Should this measure not be enough to avoid condensation of water, you must raise the cooling temperature of the cooling.

Avoid the operation of the laser, if there is water of condensation or operate with max. 50% of the total laser power until the water of condensation is totally dried. Follow strictly these instructions to avoid damages on the laser.

Gas mix

The laser beam represents a source of ignition. It is therefore mandatory to check all gas reservoirs and conduits regularly for tightness to exclude the possibility of fires or explosions.

Gas types : Laser gas mix, 7% CO₂, 28% N₂, 65% He, or other gas mix.

Safety

The possibility must be absolutely excluded that the laser light can hit the eyes or the skin of personnel. Blinding and irreversible damages in the form of burns, respectively, can result from contact with laser light. Setting and maintenance work should be carried out by skilled personnel only. Before any such work, definitely make sure that the machine and in particular the laser is off. It is good practice to keep away from the beam path even when the laser is turned off.

Follow strictly all maintenance/servicing/safety instructions in order to ensure smooth and risk-free operation of your system.

Putting the laser into operation

Before the laser is put into service, all power and control connections should be checked in order to ensure trouble free operation of the laser unit. Also check the water level in the cooling unit and proper connection of the water hoses to avoid damaging of the laser tube which can be the result of insufficient cooling. After these checks, the cooling unit is first turned on. Verify proper working pressure (max. 2 bar) and make sure that the EMEGENCY OFF switch is unlocked. The temperature should be on the cooling should be 18° C. In the next step, proper functioning of the laser control system is verified by turning the key-operated switch in position 1. The line "ZECH LASER Austria" should appear on the display. If an error message is shown instead, clear the faulty condition (if caused by an operating error), or contact our customer service in case the problem is unclear. After the above steps, the laser unit can be made ready for operating by turning the key into position 2. Also check the fan for proper functioning.

IMPORTANT WARNING:

Before attempting to clear any of the above faults, the equipment must always be turned off, and the laser must be started anew (by means of the key-operated switch) after clearing of the problem.

Faults which require work inside the laser housing (HV errors, etc.) must be handled by specially trained service personal. The high voltage used by the device is dangerous to life.

Also mind that improper repair attempts void all warranties.

ZECHLASER
A-9555 Glanegg
Austria

Phone: +43 4277 2308
+43 650 3339988
Fax: +43 4277230888

E-mail: office@laser.co.at
Web: www.laser.co.at
www.zechcut.at